



## PRODUCT SAFETY RECALL NOTICE

June 30 2022

Subject: Mini-Therm JX and Brute Mini boilers, models JX050, JX075, BJX050, and BJX075  
built from January 28, 2021 to January 12, 2022

To: Valued Laars and Bradford White Contractors

The safety of our products and our customers is the of highest importance to Laars Heating Systems (Laars). As such, please read this letter carefully as we need your assistance in this matter.

Laars has decided to launch a voluntary recall, in cooperation with the US Consumer Product Safety Commission, to field repair Mini-Therm JX and Brute Mini boiler models JX050, JX075, BJX050, and BJX075, manufactured between January 28, 2021 through January 6, 2022, for a risk of carbon monoxide leakage. No other models of Mini-Therm JX or Brute Mini boilers are included in this action.

Laars recently discovered through testing, that the manual reset, blocked vent temperature switch, part number E01201000, can malfunction, which can cause the release of gases, including carbon monoxide (CO), posing a risk of carbon monoxide poisoning.

Laars has developed switch relocation bracket kits to correct the issue. Kits include: a mounting bracket with temperature switch, hardware, installation instructions and return envelope with instructions and labels to return original switch.

Our records show that you may be an installer of a Laars Mini-Therm JX050 or JX075, or Bradford White Brute Mini BJX050 or BJX075 boiler(s). We ask for your help to repair your customer's boiler at our expense.



Laars Heating Systems will provide a parts kit to conduct the repair, including:

- All parts necessary for the field rework shipped free to the contractor address
- Step-by-step repair instructions with clear directions
- A labor allowance of up to \$200 per boiler, per completion of the rework and reporting conditions
- Return labeling and postage to return parts that will be replaced

Contractors that want to participate in these repairs, please call (888) 454-3223 with homeowner information and boiler model and serial number(s). Laars Heating Systems will review program details and arrange your service call. If for some reason you prefer not to carry out the repair, Laars Heating Systems will arrange for the repair via other resources.

Laars Heating Systems can be contacted at (888) 454-3223 from 8am to 5pm Eastern to discuss this voluntary recall that has been approved by the US Consumer Product Safety Commission or help you identify boilers that may be part of this voluntary recall.

We thank you in advance for your help in this matter.

Sincerely,

Laars Heating Systems Service Department

The following reimbursement form will be included with each repair kit that will be sent to you.



Internal use only  
Claim # \_\_\_\_\_

**Labor Claim Form - MiniTherm BJX050 - BJX075 - JX050 - JX075 - Voluntary Product Recall**

Please print clearly and complete all fields to ensure your claim is processed. Only one claim may be submitted for each form. The same boiler cannot be claimed more than once. No labor claim will be paid without completing the repair in accordance with Field Repair Instructions and receipt of old Blocked Vent Safety Switch.

**Contractor Information**

Company Name: \_\_\_\_\_  
 Company Address: \_\_\_\_\_  
 City: \_\_\_\_\_ State: \_\_\_\_\_ Zip Code: \_\_\_\_\_  
 E-mail: \_\_\_\_\_  
 Phone: \_\_\_\_\_

**Site Information**

Owner's Name: \_\_\_\_\_  
 Installation Address: \_\_\_\_\_  
 City: \_\_\_\_\_ State: \_\_\_\_\_ Zip Code: \_\_\_\_\_  
 E-mail: \_\_\_\_\_  
 Phone: \_\_\_\_\_

**Boiler & Installation Information (to be completed by the Contractor)**

Boiler Model: _____	Boiler Serial Number: _____
Kit Replacement Date: _____ (Laars Heating Systems reserves the right to contact property owners to confirm KIT installation)	
Gas Type: NG <input type="checkbox"/>	LP <input type="checkbox"/>
KIT# 1 R2088401 - BJX050 & JX050 / KIT# 2 R2088402 - BJX075 & JX075	

**By submitting this form, I confirm that KIT #1 or KIT #2 has been correctly fitted.**  
 (Please circle KIT # installed)

Contractor's Name (Printed) \_\_\_\_\_  
 Date & Signature \_\_\_\_\_

Property Owner's Name (Printed) \_\_\_\_\_  
 Date & Signature \_\_\_\_\_

If you are unable to install the R2088401 or R2088402 TURN OFF the appliance and contact Laars Heating Systems 1-888-454-3223

Please submit completed form to [warranty@laars.com](mailto:warranty@laars.com) or mail to  
 Laars Heating Systems Company, Attention Warranty, 20 Industrial Way, Rochester NH 03867

H2424100-